

UNION CARBIDE CHEMICALS & PLASTICS COMPANY INC.  
Environmental Protection Department Sistersville, WV

July 2, 1991

Memorandum to: D. R. Heintzman (via Email)

xc: R. E. Tuttle (via Email)  
J. W. Meyer  
Paul Shingleton  
E P Staff (via Email)  
Shift Coordinators  
PCB File

Re: PCB Action Report

The following PCB equipment was removed from service and placed into storage for disposal on July 1, 1991:

| Plt.<br>ID No.<br>(Tag #) | Manufacturer<br>and Type | Serial<br>Number | Disposal<br>Container<br>Number |
|---------------------------|--------------------------|------------------|---------------------------------|
| 5                         | Sprague<br>2043 PFD      | 61105            | 21                              |
| 6                         | Sprague<br>2043 PFD      | 54258            | 21                              |
| 76                        | Sprague<br>2043 PFD      | 54257            | 21                              |
| 77                        | Sprague<br>2043 PFD      | 54328            | 21                              |

The PCB storage area is located in the Silicon Grinding Building unloading bay.

Currently, there are 2 containers in storage. These containers (drum #20 and 21) have a total of seven capacitors in them.

(over)

MPM000828

EPA005249